

SAFETY DATA SHEET

1. Identification

Product identifier STRATAPRIME BRP

Other means of identification Not available.

Recommended use Not available.

Recommended restrictions None known.

Manufacturer/Importer/Supplier/Distributor information

Manufacturer

Company name CETCO, an MTI Company Address 2870 Forbs Avenue

Hoffman Estates, IL 60192

United States

Telephone General Information 800 527-9948

Website http://www.cetco.com/
E-mail safety.data@amcol.com

Emergency phone number

Americas 1.866.519.4752 (US, Canada, Mexico) 1 760 476 3962 Access Code 333562

2. Hazard(s) identification

Physical hazardsFlammable liquidsCategory 3Health hazardsSkin corrosion/irritationCategory 2

Serious eye damage/eye irritation Category 2B
Germ cell mutagenicity Category 1B
Carcinogenicity Category 1B

Specific target organ toxicity, single exposure Category 3 narcotic effects

Specific target organ toxicity, repeated Category 1

exposure

Environmental hazards Not classified.

OSHA defined hazards Not classified.

Label elements



Signal word Danger

Hazard statement Flammable liquid and vapor. Causes skin irritation. Causes eye irritation. May cause drowsiness

or dizziness. May cause genetic defects. May cause cancer.

Prevention Obtain special instructions before use. Do not handle until all safety precautions have been read

and understood. Keep container tightly closed. Keep away from heat/sparks/open flames/hot surfaces. - No smoking. Ground/bond container and receiving equipment. Use explosion-proof electrical/ventilating/lighting// equipment. Use only non-sparking tools. Take precautionary measures against static discharge. Avoid breathing mist or vapor. Wash thoroughly after handling. Use only outdoors or in a well-ventilated area. Wear protective gloves/protective

clothing/eye protection/face protection.

Response If on skin (or hair): Take off immediately all contaminated clothing. Rinse skin with water/shower.

If inhaled: Remove person to fresh air and keep comfortable for breathing. If in eyes: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. If exposed or concerned: Get medical advice/attention. Call a poison

center/doctor// if you feel unwell. Specific treatment (see on this label). If skin irritation occurs: Get medical advice/attention. If eye irritation persists: Get medical advice/attention. Take off

contaminated clothing and wash before reuse. In case of fire: Use to extinguish.

Storage Store in a well-ventilated place. Keep container tightly closed. Store in a well-ventilated place.

Keep cool. Store locked up.

Disposal Dispose of contents/container in accordance with local/regional/national/international regulations.

Hazard(s) not otherwise classified (HNOC)

None known.

Material name: STRATAPRIME BRP

6713 Version #: 03 Revision date: 07-May-2015 Print date: 07-May-2015

3. Composition/information on ingredients

Mixtures

Chemical name	Common name and synonyms	CAS number	%	
ASPHALT	PETROLEUM ASPHALT	8052-42-4	60 - < 70	
STODDARD SOLVENT		8052-41-3	30 - < 40	

^{*}Designates that a specific chemical identity and/or percentage of composition has been withheld as a trade secret.

Composition comments

For the full text of the R phrases mentioned in this Section, see Section 15.

4. First-aid measures

Inhalation Remove victim to fresh air and keep at rest in a position comfortable for breathing. If the affected

person is not breathing, apply artificial respiration. Get medical attention immediately.

Immediately flush skin with running water for at least 20 minutes. Take off immediately all Skin contact

dizziness and nausea. May cause redness and pain.

contaminated clothing. Get medical attention if irritation develops or persists. If skin irritation

occurs: Get medical advice/attention.

Immediately flush eyes with plenty of water for at least 20 minutes. Immediately flush eyes with Eye contact

plenty of water for at least 15 minutes. Remove contact lenses, if present and easy to do. Continue

rinsing. Get medical attention immediately.

Rinse mouth. If vomiting occurs naturally, have victim lean forward to reduce risk of aspiration. Get Ingestion

medical attention immediately. Do not induce vomiting without medical advice. Get medical

attention if symptoms occur.

Most important

symptoms/effects, acute and

delayed

Indication of immediate medical attention and special treatment needed

General information

Provide general supportive measures and treat symptomatically. Thermal burns: Flush with water immediately. While flushing, remove clothes which do not adhere to affected area. Call an ambulance. Continue flushing during transport to hospital. Keep victim under observation. Symptoms may be delayed. In case of ingestion, the stomach should be emptied by gastric lavage

under qualified medical supervision. Risk of product entering the lungs on vomiting after ingestion.

Exposed individuals may experience eye tearing, redness, and discomfort. Direct contact with eyes may cause temporary irritation. Vapors have a narcotic effect and may cause headache, fatigue,

Take off all contaminated clothing immediately. IF exposed or concerned: Get medical

advice/attention. Ensure that medical personnel are aware of the material(s) involved, and take

precautions to protect themselves. Wash contaminated clothing before reuse.

5. Fire-fighting measures

Suitable extinguishing media

Water fog. Foam. Dry chemical powder. Carbon dioxide (CO2). Dry chemical, foam, carbon

dioxide.

Unsuitable extinguishing

media

Water. Do not use water jet as an extinguisher, as this will spread the fire.

Specific hazards arising from

the chemical

Vapors may form explosive mixtures with air. Vapors may travel considerable distance to a source of ignition and flash back. During fire, gases hazardous to health may be formed.

Special protective equipment and precautions for firefighters Self-contained breathing apparatus and full protective clothing must be worn in case of fire.

Fire-fighting

equipment/instructions

In case of fire and/or explosion do not breathe fumes. Use standard firefighting procedures and consider the hazards of other involved materials. Move containers from fire area if you can do so without risk. Do not point solid water stream directly into burning oil to avoid spreading. Cool containers with flooding quantities of water until well after fire is out.

Specific methods

Use standard firefighting procedures and consider the hazards of other involved materials. Move containers from fire area if you can do so without risk. In the event of fire and/or explosion do not breathe fumes.

General fire hazards

Vapors may form explosive mixtures with air. Vapors are heavier than air and may travel along the ground to some distant source of ignition and flash back. Flammable liquid and vapor.

6. Accidental release measures

Personal precautions, protective equipment and emergency procedures

Keep unnecessary personnel away. Keep people away from and upwind of spill/leak. Keep out of low areas. Eliminate all ignition sources (no smoking, flares, sparks, or flames in immediate area). Wear appropriate protective equipment and clothing during clean-up. Do not touch damaged containers or spilled material unless wearing appropriate protective clothing. Avoid inhalation of vapors or mists. Ventilate closed spaces before entering them. Local authorities should be advised if significant spillages cannot be contained. For personal protection, see section 8 of the SDS.

Material name: STRATAPRIME BRP

Methods and materials for containment and cleaning up

Eliminate all ignition sources (no smoking, flares, sparks, or flames in immediate area). Take precautionary measures against static discharge. Use only non-sparking tools. Keep combustibles (wood, paper, oil, etc.) away from spilled material. Prevent entry into waterways, sewers, basements or confined areas.

Large Spills: Stop leak if you can do so without risk. Dike the spilled material, where this is possible. Cover with plastic sheet to prevent spreading. Absorb with earth, sand or other non-combustible material and transfer to containers for later disposal. Following product recovery, flush area with water.

Small Spills: Wipe up with absorbent material (e.g. cloth, fleece). Clean surface thoroughly to remove residual contamination.

Environmental precautions

Never return spills to original containers for re-use. For waste disposal, see section 13 of the SDS. Avoid discharge into drains, water courses or onto the ground. Do not flush into surface water or sanitary sewer system. Runoff from fire control or dilution water may cause pollution.

7. Handling and storage

Precautions for safe handling

Obtain special instructions before use. Do not handle until all safety precautions have been read and understood. Vapors may form explosive mixtures with air. Do not handle, store or open near an open flame, sources of heat or sources of ignition. Protect material from direct sunlight. Do not handle or store near an open flame, heat or other sources of ignition.

Do not smoke. Vapors are heavier than air and may spread along floors. Use spark-proof tools and explosion-proof equipment. Take precautionary measures against static discharges. All equipment used when handling the product must be grounded. Use non-sparking tools and explosion-proof equipment. Avoid breathing mist or vapor. Avoid contact with skin. Avoid contact with eyes. Avoid prolonged exposure. Avoid contact with clothing. Provide adequate ventilation. Wear appropriate personal protective equipment. Observe good industrial hygiene practices.

Conditions for safe storage, including any incompatibilities

Store locked up. Store in a place accessible by authorized persons only. Keep away from heat and sources of ignition. Prevent electrostatic charge build-up by using common bonding and grounding techniques. Keep the container tightly closed and dry. Store in original tightly closed container. Store in a cool, dry place out of direct sunlight. Store in a well-ventilated place. Keep this material away from food, drink and animal feed. Refrigeration recommended. Store away from incompatible materials (see Section 10 of the SDS). Keep out of the reach of children.

Keep in an area equipped with sprinklers.

8. Exposure controls/personal protection

Occupational exposure limits

US. OSHA Table Z-1 Limits for Air Components	Type	Value	
STODDARD SOLVENT (CAS 8052-41-3)	PEL	2900 mg/m3	
,		500 ppm	
US. ACGIH Threshold Limit Values	S		
Components	Туре	Value	Form
ASPHALT (CAS 8052-42-4)	TWA	0.5 mg/m3	Inhalable fraction.
STODDARD SOLVENT	TWA	100 ppm	
(CAS 8052-41-3)			
US. NIOSH: Pocket Guide to Chem	ical Hazards		
Components	Туре	Value	Form
ASPHALT (CAS 8052-42-4)	Ceiling	5 mg/m3	Fume.
STODDARD SOLVENT (CAS 8052-41-3)	Ceiling	1800 mg/m3	

Biological limit values

No biological exposure limits noted for the ingredient(s).

TWA

Appropriate engineering controls

Explosion-proof general and local exhaust ventilation. Eye wash facilities and emergency shower must be available when handling this product.

350 mg/m3

Individual protection measures, such as personal protective equipment

Eye/face protection Wear eye/face protection. If splashes are likely to occur, wear: Face-shield. Goggles.

Hand protection Wear appropriate chemical resistant gloves.

Other Wear appropriate chemical resistant clothing. The use of neoprene gloves is recommended.

Respiratory protection In case of insufficient ventilation, wear suitable respiratory equipment. Use an organic vapor respirator for concentrations exceeding the Occupational Exposure Limit. Special applications may

necessitate the use of more stringent respiratory protection equipment.

Material name: STRATAPRIME BRP

6713 Version #: 03 Revision date: 07-May-2015 Print date: 07-May-2015 3 / 8

Thermal hazards Wear appropriate thermal protective clothing, when necessary.

General hygiene considerations

When using, do not eat, drink or smoke. Always observe good personal hygiene measures, such as washing after handling the material and before eating, drinking, and/or smoking. Routinely wash work clothing and protective equipment to remove contaminants. Eye wash fountain and emergency showers are recommended. Shower or bathe at the end of working.

9. Physical and chemical properties

Appearance

Liquid. Physical state Liquid. **Form**

Black. or Brown. Color Odor Petroleum **Odor threshold** Not available. Not available.

Melting point/freezing point -94 °F (-70 °C) estimated Initial boiling point and boiling 560.7 °F (293.72 °C) estimated

range

103.0 °F (39.4 °C) Tag Closed Cup Flash point

Evaporation rate

Not available Flammability (solid, gas) Upper/lower flammability or explosive limits

Flammability limit - lower

0.9 % estimated

Flammability limit - upper

6 % estimated

(%)

Not available. Explosive limit - lower (%) Explosive limit - upper (%) Not available. Vapor pressure 2 hPa estimated

Vapor density 49

Not available. Relative density

Solubility(ies)

Not available. Solubility (water) Not available. **Partition coefficient**

(n-octanol/water)

Auto-ignition temperature 745.75 °F (396.53 °C) estimated

Decomposition temperature Not available. Not available. Viscosity

Other information

0.91 g/cm3 estimated Density Flammability class Combustible II estimated

Flash point class Combustible II Specific gravity 0.91 estimated VOC (Weight %) < 349 g/l

10. Stability and reactivity

The product is stable and non-reactive under normal conditions of use, storage and transport. Reactivity

Chemical stability This is a stable material.

Possibility of hazardous

reactions

Will not occur. Hazardous polymerization does not occur.

Conditions to avoid Heat, flames and sparks. Avoid temperatures exceeding the flash point. Contact with incompatible

materials.

Strong oxidizing agents. or Water. Incompatible materials

Hazardous decomposition

products

Upon decomposition, this product emits oxides of sulfur, carbon monoxide, carbon dioxide and/or low molecular weight hydrocarbons.

11. Toxicological information

Information on likely routes of exposure

Ingestion Expected to be a low ingestion hazard.

Material name: STRATAPRIME BRP 6713 Version #: 03 Revision date: 07-May-2015 Print date: 07-May-2015

Vapors have a narcotic effect and may cause headache, fatigue, dizziness and nausea. Inhalation

Prolonged inhalation may be harmful.

Skin contact Causes skin irritation. Eye contact Causes eye irritation.

Symptoms related to the physical, chemical and toxicological characteristics

Exposed individuals may experience eye tearing, redness, and discomfort. Skin irritation. May cause redness and pain. Symptoms of overexposure may be headache, dizziness, tiredness, nausea and vomiting.

Information on toxicological effects

Acute toxicity Narcotic effects.

Product Species Test Results

STRATAPRIME BRP (CAS Mixture)

Acute Dermai

LD50 Rabbit 3077 mg/kg

* Estimates for product may be based on additional component data not shown.

Skin corrosion/irritation Serious eye damage/eye Causes skin irritation. Causes eye irritation.

irritation

Respiratory or skin sensitization

Respiratory sensitization Not available

Skin sensitization This product is not expected to cause skin sensitization.

Germ cell mutagenicity May cause genetic defects.

Carcinogenicity May cause cancer.

IARC Monographs. Overall Evaluation of Carcinogenicity

ASPHALT (CAS 8052-42-4) 2B Possibly carcinogenic to humans.

Reproductive toxicity This product is not expected to cause reproductive or developmental effects.

Specific target organ toxicity -

single exposure

Narcotic effects.

Specific target organ toxicity -

repeated exposure

Not classified.

Aspiration hazard Not available.

Chronic effects Prolonged inhalation may be harmful. Prolonged or repeated exposure may cause lung injury.

Prolonged exposure may cause chronic effects. Repeated or prolonged exposure may cause skin

irritation and dermatitis, due to degreasing properties of the product.

12. Ecological information

Ecotoxicity Components of this product are hazardous to aquatic life. In high concentrations, this product may

be dangerous to aquatic life and fouling to shorelines.

No data is available on the degradability of this product. Persistence and degradability

Bioaccumulative potential No data available. Partition coefficient n-octanol / water (log Kow)

3.16 - 7.15 STODDARD SOLVENT

No data available. Mobility in soil

Other adverse effects No other adverse environmental effects (e.g. ozone depletion, photochemical ozone creation

potential, endocrine disruption, global warming potential) are expected from this component.

13. Disposal considerations

Disposal instructions Collect and reclaim or dispose in sealed containers at licensed waste disposal site. This material

and its container must be disposed of as hazardous waste. Do not allow this material to drain into sewers/water supplies. Do not contaminate ponds, waterways or ditches with chemical or used container. Dispose of contents/container in accordance with local/regional/national/international

regulations.

Local disposal regulations Dispose in accordance with all applicable regulations.

Hazardous waste code The waste code should be assigned in discussion between the user, the producer and the waste

disposal company.

Waste from residues / unused

products

Dispose of in accordance with local regulations. Empty containers or liners may retain some product residues. This material and its container must be disposed of in a safe manner (see:

Disposal instructions).

Material name: STRATAPRIME BRP

SDS US 6713 Version #: 03 Revision date: 07-May-2015 Print date: 07-May-2015

Contaminated packaging

Empty containers should be taken to an approved waste handling site for recycling or disposal. Since emptied containers may retain product residue, follow label warnings even after container is emptied.

14. Transport information

DOT

UN number UN1268

UN proper shipping name Petroleum distillates, n.o.s. (STODDARD SOLVENT)

Transport hazard class(es)

Class 3
Subsidiary risk Label(s) 3
Packing group III

Special precautions for user Read safety instructions, SDS and emergency procedures before handling.

Special provisions 144, B1, IB3, T4, TP1, TP29

Packaging exceptions 150
Packaging non bulk 203
Packaging bulk 242

IATA

UN number UN1268

UN proper shipping name Petroleum distillates, n.o.s. (STODDARD SOLVENT)

Transport hazard class(es)

Class 3
Subsidiary risk Label(s) 3
Packing group III
Environmental hazards No.

Special precautions for user Read safety instructions, SDS and emergency procedures before handling.

Other information

Passenger and cargo

aircraft

Forbidden.

Forbidden.

Cargo aircraft only

IMDG

UN number UN1268

UN proper shipping name Petroleum distillates, n.o.s. (STODDARD SOLVENT)

Not available.

Transport hazard class(es)

Class 3
Subsidiary risk Label(s) 3
Packing group III
Environmental hazards

Marine pollutant No.

EmS Not available.

Special precautions for user Read safety instructions, SDS and emergency procedures before handling.

Transport in bulk according to Annex II of MARPOL 73/78 and the IBC Code

lile ib



Material name: STRATAPRIME BRP
6713 Version #: 03 Revision date: 07-May-2015 Print date: 07-May-2015

SDS US



15. Regulatory information

US federal regulations This product is a "Hazardous Chemical" as defined by the OSHA Hazard Communication

Standard, 29 CFR 1910.1200.

OSHA Process Safety Standard: This material is not known to be hazardous by the OSHA Highly

This product does not contain a chemical known to the State of California to cause cancer, birth

Hazardous Process Safety Standard, 29 CFR 1910.119.

All components are on the U.S. EPA TSCA Inventory List.

CERCLA/SARA Hazardous Substances - Not applicable.

CERCLA Hazardous Substance List (40 CFR 302.4)

ASPHALT (CAS 8052-42-4) LISTED

US. OSHA Specifically Regulated Substances (29 CFR 1910.1001-1050)

Superfund Amendments and Reauthorization Act of 1986 (SARA)

Yes

Immediate Hazard - Yes **Hazard categories**

Delayed Hazard - Yes Fire Hazard - Yes Pressure Hazard - No Reactivity Hazard - No

SARA 302 Extremely

hazardous substance

SARA 311/312 Hazardous Yes

chemical

SARA 313 (TRI reporting)

Not regulated.

Other federal regulations

Clean Air Act (CAA) Section 112 Hazardous Air Pollutants (HAPs) List

Not regulated.

Clean Air Act (CAA) Section 112(r) Accidental Release Prevention (40 CFR 68.130)

Not regulated.

Safe Drinking Water Act

(SDWA)

US state regulations

Not regulated.

defects or other reproductive harm.

US - Pennsylvania RTK - Hazardous Substances: Listed substance

STODDARD SOLVENT (CAS 8052-41-3)

US. Massachusetts RTK - Substance List

ASPHALT (CAS 8052-42-4)

STODDARD SOLVENT (CAS 8052-41-3)

US. New Jersey Worker and Community Right-to-Know Act

Not regulated.

US. Rhode Island RTK

Not regulated.

US. California Proposition 65

WARNING: This product contains a chemical known to the State of California to cause cancer.

US - California Proposition 65 - CRT: Listed date/Carcinogenic substance

ASPHALT (CAS 8052-42-4) Listed: January 1, 1990

International Inventories

Country(s) or region Inventory name On inventory (yes/no)* Australia Yes

Australian Inventory of Chemical Substances (AICS) Material name: STRATAPRIME BRP SDS US

Country(s) or region	Inventory name	On inventory (yes/no)*
Canada	Domestic Substances List (DSL)	Yes
Canada	Non-Domestic Substances List (NDSL)	No
China	Inventory of Existing Chemical Substances in China (IECSC)	Yes
Europe	European Inventory of Existing Commercial Chemical Substances (EINECS)	Yes
Europe	European List of Notified Chemical Substances (ELINCS)	No
Japan	Inventory of Existing and New Chemical Substances (ENCS)	Yes
Korea	Existing Chemicals List (ECL)	Yes
New Zealand	New Zealand Inventory	Yes
Philippines	Philippine Inventory of Chemicals and Chemical Substances (PICCS)	Yes

United States & Puerto Rico Toxic Substances Control Act (TSCA) Inventory Yes
*A "Yes" indicates that all components of this product comply with the inventory requirements administered by the governing country(s)

16. Other information, including date of preparation or last revision

Issue date07-August-2014Revision date07-May-2015

Version # 03

Further information This safety datasheet only contains information relating to safety and does not replace any product

information or product specification.

HMIS® ratings Health: 2*

Flammability: 2 Physical hazard: 0

NFPA ratings Health: 2

Flammability: 2 Instability: 0

Disclaimer The information provided in this Safety Data Sheet is correct to the best of our knowledge,

information and belief at the date of its publication. The information given is designed only as a guidance for safe handling, use, processing, storage, transportation, disposal and release and is not to be considered a warranty or quality specification. The manufacturer expressly does not make any representations, warranties, or guarantees as to its accuracy, reliability or completeness nor assumes any liability, for its use. It is the user's responsibility to verify the suitability and

completeness of such information for each particular use.

Third party materials: Insofar as materials not manufactured or supplied by this manufacturer are used in conjunction with, or instead of this product, it is the responsibility of the customer to obtain, from the manufacturer or supplier, all technical data and other properties relating to these and other materials and to obtain all necessary information relating to them. No liability can be accepted in respect of the use of this product in conjunction with materials from another supplier. The information relates only to the specific material designated and may not be valid for such material used in combination with any other materials or in any process, unless specified in the text. The information in the sheet was written based on the best knowledge and experience

currently available.

Revision Information Physical & Chemical Properties: Multiple Properties

GHS: Classification

6713 Version #: 03 Revision date: 07-May-2015 Print date: 07-May-2015

A "No" indicates that one or more components of the product are not listed or exempt from listing on the inventory administered by the governing country(s).